

ROCK GARNET TRADING (SA0079856-X) No. 8-1, Jalan Palma Raya, Bandar Botanic, 41200 Klang, Selangor Darul Ehsan Tel:+603-3318 8984 Fax: +603-3325 8984 Web: www.rockgarnet.com

ABRASIVE TEST REPORT

| STANDARD | SA 2 | | |
|----------------------|----------------------------------|--|--|
| METHORD | MANUAL BLASTING | | |
| SUBSTRATE | MILD STEEL | | |
| PROJECT TITLE | | | |
| CLIENT/OWNER | | | |
| SUPPLIER | ROCK GARNET TRADING | | |
| TEST LOCATION / YARD | SUNGAI CHOH, RAWANG | | |
| PERSON PRESENT | MR.KUMARAN | | |
| DATE OF TEST | 17 th September 2013. | | |
| ABRASIVE TYPE | LTR 01 & LTR 02 | | |

TEST RESULTS

| | INSPECTION CRITERIA | OBSERVATION | | REMARKS |
|--|--|------------------------------|------------------------------|--------------------------|
| | | REQUIRED | ACTUAL | |
| | ABRASIVE SIZE LTR 01 ABRASIVE SIZE LTR 02 | 1 mm - 2 mm 0.6 mm - 2 mm | 1 mm - 2 mm 0.6 mm - 2 mm | ACCEPTABLE |
| | CLEANLINESS | Sa2 | Sa 2 | ACCEPTABLE |
| | DUST LEVEL | Level 0-3 | Level 1 | ACCEPTABLE |
| | SOLUBLE WATER TEST/ DISCOLORATION | N/A | N/A | N/A |
| | RESIDUE/GREASE/OIL | Shall not contain | Does not contain | ACCEPTABLE |
| | CONDUCTIVY TEST | <150µS/cm2 | 65μS/cm2 (A) 53μS/cm2 (B) | ACCEPTABLE ACCEPTABLE |
| | SURFACE PROFILE – 01 | 40~70µm | 70µm | ACCEPTABLE |
| | SURFACE PROFILE – 02 | 40~70μm | 60µm | ACCEPTABLE |

Notes:


- 1) Acceptance surface profile 40~70µm (micron) for external.
- 2) Test area taken randomly and the results serve as a guide only owing to contraption and distribution of chloride may not be uniform throughout the substrates.
- distribution of chloride may not be uniform unoughout the succentre.
 This test report is prepared on the inspection made as the above date and from our best knowledge, it is issued without prejudice.



Witness by: JAIZAN BIN TUSHAN COATING INSPECTOR NACE LEVEL 1 CIP NO 252301 HIP: 011-15719747 Coating Inspector Mr. Jaizan Bin Tushan

(No. 906799-K) Low Hites by an Perindustrian Olak Lempit, Mukim Tanjung 12, 42700 Banting; Selangor Darul Ehsan. Tel: 603-31826588 Fax: 603-31826599


Lion Titco Recourses Mr. Samson




INITIAL OF MILD STEEL PLATE BEFORE BLASTING



BLASTING IN PROGRESS



INITIAL AFTER BLASTING ABBRASIVE 'A'





THE MODE OF READING PROFILE GAUGE ON THE SURFACE 'A'




THE MODE OF READING PROFILE GAUGE ON THE SURFACE 'B'




THE MODE OF READING SALT TEST FOR INITIAL 'A'



THE MODE OF READING SALT TEST FOR FINAL 'A'



THE VIEW OF BRESTEL FATCH A AFTER TEST




THE VIEW OF BRESTLE PATCH 'B' AFTER TEST



THE MODE OF READING SALT TEST FOR INITIAL 'B'



THE MODE OF READING SALT TEST FOR FINAL 'B'



THE VIEW OF RESULT DUST LEVEL TEST